

HIGH PRESSURE AIR VALVE


ES Válvula de Aire para Alta Presión DE Luftventil für Hochdruck

IT Valvola d'Aria per Alte Pressioni PT Válvula de Ar para Alta Pressão FR Soupape à Air Pour Haute Pression


● Cad Insertion Point

IMPORTANT !

Triple air entrance to ensure balanced opening.
Triple entrada de aire para asegurar una apertura equilibrada.
Dreifacher Lufteinlaß um ein ausgeglichene Öffnung sicherzustellen.
L'ingresso dell'aria è triplo per assicurare un'apertura equilibrata.
Tripla entrada de ar para uma abertura equilibrada.
Triple entrée d'air pour une ouverture équilibrée.



Mat. INOX 1.4034
Hardened 51±3 HRC





Ref.	A	B	D	E	F	H
VH.065215	6	5.4	1.9	4	5.8	0.25
VH.086515	8	6.7	2	5	7.8	0.75
VH.121015	12	9.7	2.7	5	11.8	1

Installation Guidelines

Consejos de Instalación · Richtlinien zur Installation · Consigli di Installazione · Instruções de Instalação · Mode d'Installation

Maximum Injection
Pressure: 2500 Kgs/cm²
(1BAR ~ 1kg/cm²)



IMPORTANT !

Maximum machining allowed.
Medida máxima de mecanizado.
Maximale Bearbeitung erlaubt.
Quota massima di lavorazione.
Medida máxima a maquinar.
Valeur maximum d'usinage.



VH

ACCESSORIES



Max.
150°C

Min.
2 BARS
Max.
10 BARS